

# Tampering Switch Hold Add Process

Scenario: TDSP found Tampering at Customer's Premise –TDSP Adds Tampering Switch Hold Indicator.

Transactions: 814\_20 and 814\_21 (ERCOT to TDSP Only)

Effective: June 2012

