

# **ERCOT Winter Weatherization Workshop Opening Remarks**

David Kezell
Director, Weatherization and Inspection

October 28, 2024


## Looking back on Weather Emergency Preparedness in ERCOT

- Phase I of 16 TAC § 25.55, adopted on October 19, 2021.
- Phase II adopted on September 29, 2022, adding summer standards.
- Beginning in 2023
  - Weather zone-specific cold and hot conditions at which MPs must implement measures reasonably expected to ensure sustained operation.
  - List of all cold- and hot-weather-critical components.
- This winter season will be our fourth with a PUCT rule in place.


Inspections	Resources	TSP Facilities	Total
Winter '21-'22	302	22	324
Winter '22-'23	634	140	774
Summer '23	208	342	550
Winter '23-'24	340	129	469
Summer '24	417	358	775
Total to Date	1901	991	2892



## **Our Collective Efforts are Producing Results**



**Key Takeaway:** Winter Storm Heather was the third coldest, and second most long lasting of the significant winter storms shown here.



**Key Takeaway:** Non-IRR outages during WS Heather (Jan 2024) remained lower than WS Elliott (Dec 2022) and WS Uri (Feb 2021).



## **On-going Collaboration**

- Continued diligence in understanding and complying with rule provisions and seeking to apply best practices will deliver high reliability when it is needed most.
- New Resource Entities & TSPs will benefit by focusing on compliance from the start.
- The Commission does not hesitate to open enforcement investigations. These can and do result in administrative penalties.

#### Logistical Items

- Please set AR & BAR spam filters to allow email from <a href="ercot@servicenowservices.com">ercot@servicenowservices.com</a> and assure timely responses to Notices of Inspections (NOI) and keep your AR/BAR registrations current.
- Please submit Declarations of Weather Preparedness (DoWP) on the portal between 11/1 & 12/1/24.
- Take advantage of the <u>recorded training</u> and the <u>Market Participant Portal User Guide</u> for interactions on the ERCOT Weatherization and Inspection Portal.
- We have retired previously used specific-use email accounts, as well as the use of DocuSign, with that functionality now residing on the portal.



## **Other Helpful Suggestions**

- When you submit a DoWP with the notarized signature of your highest ranking official, that person has attested to the accuracy and veracity of the document package.
- The design basis cold temperature and wind speed in Appendix A are facility specific.
   These values should be thermal design criteria and not include wind speeds associated with structural design.
- Ideally, multiple people from each Market Participant should be credentialed and trained to use the portal.
- Weatherization support cases can be used for questions and to request help.
- On inspection day, be prepared and have personnel who can explain site practices as well as answer questions present.
- If you have a simple compliance deficiency, it is to your advantage to remedy it quickly.
- ERCOT Weatherization and Inspection staff will support your compliance efforts.



## **Comments on Reasonable Expectation of Sustained Operation**

- Each Resource or substation/switchyard is now required to meet 16 TAC 25.55(c)(1)(B) or (f)(1)(b) which establish weather zone-specific wind chill levels.
- Any additional preparation measures that could reasonably be expected to ensure sustained operations at these conditions must be implemented.

lack lack lack				
Weather Zone	95 <sup>th</sup> Percentile Minimum Average 72-Hour Wind Chill	99 <sup>th</sup> Percentile Minimum Average 72-Hour Wind Chill		
North	-5.0°	-10.5°		
North Central	-0.5°	-5.1°		
West	0.3°	-7.6°		
Far West	1.3°	-5.2°		
East	4.4°	-0.7°		
Coast	18.1°	4.1°		
South Central	8.4°	3.8°		
Southern	16.3°	11.7°		
Valley	20.0°	16.9°		
Panhandle	-17.6°	-19.6°		

Winter Requirement

Table 72: Historical Minimum 72-Hour Average Wind Chill Data

- If a failure to sustain operations occurs at conditions less severe than those on the chart, the expectation is that MPs will determine the cause and remedy it as soon as practicable.
- Without a remedy in place, it is difficult to assert that one reasonably expect to ensure operations going forward.



# **Moving Forward Together**

- Continued diligence in complying with rule provisions and seeking to apply best practices will allow us to deliver high levels of reliability for Texas when most needed.
- The ERCOT Weatherization & Inspection Market Participant Portal will be available to MPs on November 1, 2024 for submission of DoWPs.
- Please assure that roles are added to the digital certificates of appropriate personnel by your company's User Security Administrator (USA).
  - SN\_M\_W\_MGR\_ECEII for managers with authority to submit
  - SN\_M\_W\_VIEW\_ECEII for employees with read-only privileges
  - Do not select both as the more restrictive read-only will govern
- Best Practices, user guide, and many other documents are available on <u>Winter Weather Readiness (ercot.com)</u>
- Thank you in advance for your excellent service in preparing the grid to withstand weather emergencies!

